

**To:** Way, Steven[way.steven@epa.gov]  
**From:** Matt Francis  
**Sent:** Wed 9/3/2014 6:39:22 PM  
**Subject:** Fwd: Trackhoe  
removed.txt

Yes?

Sent via the Samsung Galaxy Note® 3, an AT&T 4G LTE smartphone

----- Original message -----

From: Bob Heeter  
Date: 09/03/2014 11:11 AM (GMT-07:00)  
To: Matt Francis  
Subject: Trackhoe

Matt, do you know the date that the 320 trackhoe might be available for our use at the Gold King. You have probably noticed the chatter about getting the steel sets coated, there will be more. We will also want to look at the collar braces, tie rods and nuts, and structural bolts and nuts. Galvanized or stainless are a couple of options. On the drawings it indicates that the split set bolts and plates will be SS-39 Galvanized, can we assume the mine matts will need to be galvanized as well?

Thank you,  
Bob Heeter  
Superintendent  
[cid:image001.jpg@01CFC764.122D2800]  
HARRISON WESTERN CONSTRUCTION CORPORATION  
1208 Quail Street  
Lakewood, Colorado 80215  
T (303) 234.0273 x202 | C (775-340-1776)  
F (303) 237.9868 | [www.harrisonwestern.com](http://www.harrisonwestern.com)<<http://www.harrisonwestern.com>>

---

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. The sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you